


Drilling & Tapping Machine

PARTS LIST



1 Nut	15 Nut	29 Pin	42 Bolt	56 Nut
2 Spring Case	16 Ball Bearing	30 Clamp Bolt	43 Base	57 Bolt
3 Helical Spring	17 Thrust Bearing	31 Table Brachet	44 Slide Bar	58 Cord
4 Clamp Bolt	18 Ball Bearing	32 Table	45 Bar	59 Switch
5 Clamp Piece	19 Pulley Nut	33 Handle	46 Nut	60 Machine Screw
6 Feed Dial	20 Spindle Pulley	34 Set Screw	47 Shifter Piece	61 Electronic Box
7 Feed Shaft	21 Spline Sleeve	35 Worm	48 Shifter	62 Electronic Shell
8 Grip	22 Spindle	36 Pin	49 Set Screw	63 Small Switch Cov
9 Handle of Grip	23 Sleeve	37 Gear	50 Shifter Bar	64 Screw
10 Ring	24 Machine Screw	37 Gear	51 Clamp Bolt	65 Small Basic Swit
11 Ball Bearing	25 Belt Cover	38 Column	52 V-Belt	66 Big Basic Switch
12 Bearing Space	26 Body	39 Ring	53 Motor Pulley	67 Screw
13 Ball Bearing	27 Set Screw	40 Set Screw	54 Set Screw	
14 Snap Ring	28 Bolt	41 Rack	55 Motor Base	