



- | | | | | |
|------------------|-------------------|------------------|------------------|------------------|
| 1 Nut | 13 Ball Bearing | 25 Belt Cover | 37 Gear | 49 Set Screw |
| 2 Spring Case | 14 Snap Ring | 26 Body | 38 Column | 50 Shifter Bar |
| 3 Helical Spring | 15 Nut | 27 Set Screw | 39 Ring | 51 Clamp Bolt |
| 4 Clamp Bolt | 16 Ball Bearing | 28 Bolt | 40 Set Screw | 52 V-Belt |
| 5 Clamp Piece | 17 Thrust Bearing | 29 Pin | 41 Rack | 53 Motor Pulley |
| 6 Feed Dial | 18 Ball Bearing | 30 Clamp Bolt | 42 Bolt | 54 Set Screw |
| 7 Feed Shaft | 19 Pulley Nut | 31 Table Bracket | 43 Base | 55 Motor Base |
| 8 Grip | 20 Spindle Pulley | 32 Table | 44 Slide Bar | 56 Nut |
| 9 Handle of Grip | 21 Spline Sleeve | 33 Handle | 45 Bar | 57 Bolt |
| 10 Ring | 22 Spindle | 34 Set Screw | 46 Nut | 58 Cord |
| 11 Ball Bearing | 23 Sleeve | 35 Worm | 47 Shifter Piece | 59 Switch |
| 12 Bearing Space | 24 Machine Screw | 36 Pin | 48 Shifter | 60 Machine Screw |